





## Laborator de caracterizare materiale electrotehnice

Initial



Actual



### Lucrari executate in cadrul proiectului:

- re compartimentare;
- instalare pod rulant;
- postament antivibratie;
- zugraveka;
- racordari la retea electrica, apa, gaze.
- recopmartimentare cu zidarie;
- tavan fals,
- zugraveka;
- racordari la retea electrica, apa, gaze.